Sanitized Copy Approved for Release 2011/08/11: CIA-RDP78-03424A000200020022-5	
	25X1
	25 <b>X</b> 1
Subject: Maeting on H-2051  / Antanna Hork at  on 16 Decamber 1955	25X1
Propont:	25X1

A discussion of the packaging and nochanical aspects of the antenna design brought out several problems. Some of the problems require nochanical layout work to be done by so arrive at an acceptable solution. Some others depart upon conclusions to be reached with the customer.

25X1

The following ware the points discussed and the conclusions reached based on the data at hand.

- 1. A full size model of the low band dipoles (70 to 170 me and 170 to 400 me) including reflecting screen was displayed. The cite of the model seemed reasonable enough for use on a FT beat.
- 2. The base area of the antonna structure is appreximately a mine foot square.
- 3. The samples of the high band horns (10 to 20 Kms and 20 to 40 Kms) have been fabricated without electroforming. They are to be tested electrically.
- 4. A sample of the "I" band horn has been fabricated. It has been tosted as
  to VStR. The VStR spec. has been achieved except at low end of the frequency
  range. This is being investigated.
- 5. The crystal shuttor problem has been satisfactorily solved by the use of a Danbury-Knudson coaxial suited at frequencies up to 5 kms. Above 5 kms other methods are to be tried. The possibilities are; a camera type shutter arrangement or an over-the-mouth solonoid operated metal plate.
- 6. A Sylvania 1N446 (D799) is to be used in the 20-40 Kms band, price \$47.50.
- 7. The following points are to be discussed with the swatemer:
  - e. Effect of sloping the low band dipoles, following the antenna superstructure.
  - b. Height of low band dipoles above cabia top.

# CONFIDENTIAL

Sanitized Copy Approved for Release 2011/08/11: CIA-RDP78-03424A000200020022-5

- e. Interference effects on patterns caused by existing antennas aboard ship.
- d. Location of console unit on ship to determine cable runs and locations.
- 8. Mathed of mounting antenna superstructure to cabin top.
- f. Color of radoma
- g. Desirability for maintenance purposes of a power socket and availability of power from ship's supply.

The following are the suggestions for machanical design of the antenna structure:

### l. Upper Section:

- a. The honeycomb construction of the radome is not to be carbon filled.
- b. There is to be a permanent mounting for the horns.
- c. The radons cover is to be resevable.
- d. The horns are to be fitted from inside through the honeycomb.

#### 2. Center Jaction:

- a. There is to be a 15 to 18 inch square column.
- b. There are to be hinges on one to four sides. Four is preferred.
- c. Electrical components are to be on the rear side of the hinged members.
- d. The hinged panels are to be made of carbon filled fiberglas.
- e. All cables are to be inside rectangular column, possibly in conduit.
- f. The helical antennas are to be mounted on the outside of the hinged panels.
- g. The exterior conical radoms is to be removable in sections.

#### 3. Bottom section:

- a. There is to be a fiberglas inverted dome at the lower end of the center section to reduce air turbulence.
- b. Electrical components for bands 1 and 2 are to be housed within this dome.
- c. Access to the components are to be via trapdoors cut in the dome.
  Components may be mounted on inside of the door.
- d. Except for trapdoors the dome section is a permanent part of the structure.

CONFIDENTIAL

## -3-CONFIDENTIAL

#### 4. Lower Framework:

- a. Low band (bands 1 and 2) dipoles to be designed as appearing to be part of the antenna superstructure.
- b. Welded aluminum tubing is preferable for construction of the superstructure.
- c. The method of bringing down the cables from the radome is not definite. There are two possibilities; using a contral cable conduit or fastening the cables to one of the superstructure legs.

#### 5. General:

- a. The radoms is not to be painted and should include notice stating same. The color of the radoms is due to a dye added in the manufacturing process.
- b. The finish on metallic surfaces of the antenna structure are to be in accordance with ML-E-16,400.
- c. The entire structure is to be weather-proofed with emphasis on seas spray-proofing.

25X1

25X1

d. Ladder hooks for maintenance purposes are to be included in the design of the structure.

Those	a Present			

**CONFIDENTIAL**